



**GALFER USA**

310 Irving Drive  
Oxnard, CA 93030  
USA

**FK003D242R**

**Rear ZRX Banjo Installation WARNING:**



When installing the rear brake line on your ZRX1100 or 1200, please make sure the rear master cylinder banjo is facing the same way your stock banjo was before. Failure to do so will break the Galfer banjo, and cause the brake fluid to leak. Please remember not to torque the banjos over 15 foot lbs.

If you have any questions please call us at **(800) 685-6633**

Thanks,  
Galfer Brakes