

PDM60

Options setup guide




Purpose: To assist a PDM60 user in COM port selection

The first time you use the PDM60 dashboard, you need to set your "Options". There are two things that need to be done.

- 1) Assign a COM port
- 2) Assign a Programming Tool

To set these up, open the dashboard program, and in the top left corner, click on "File", and go to..... "Options"

Click here and go to:
"Options"




..... the dialogue box shown below will open up.

COM port selection:

Click the arrow, and select the correct COM port for the location where you have plugged the programming cable into your computer.

Warning!! Incorrect COM port assignment may yield false positive "Programming Successful" message upon programming.



Programming Tool:

This should always be set to...
"PDM60 Programming Cable"

An easy way to make sure you have the correct COM port is this.

First Step

- a) UNPLUG the programming cable from your computer
- b) Open the PDM60 dashboard, and go to "File >>> Options"
- c) Click the COM port arrow
- d) Note the COM ports are showing up
- e) Close the dashboard program completely

Now.....

- f) PLUG IN the programming cable
- g) Open the PDM60 dashboard, and go to "File >>> Options"
- h) Click the COM port arrow
- i) Look for a COM ports that was not showing up in the first step. Select that COM port, as it should be the correct port to use.

If you're still having issues, go to PDM60.com and view the Quick Start sheet and the troubleshooting document. If you still need help, feel free to call our office and speak with us.

www.PDM60.com

Rowe Electronics
515-981-5504

Thank You!!

